Photo 1 – Deteriorated crossties and insufficient ballast on mainline. Greenville, Texas.

Photo 2 – Deteriorated crossties on mainline. Hunt County, Texas.

Photo 3 – Poor track alignment and profile. Greenville, Texas.

Photo 4 – Poor track alignment and profile. Hopkins County, Texas.

Photo 5 – Poor track alignment and profile. Franklin County, Texas.

Photo 6 – Insufficient support of rail and joints on bridge approach. Hunt County, Texas.

Photo 7 – Poor track profile at bridge approach. Hopkins County, Texas.

Photo 8 – Unsupported rail and joints on mainline. Hunt County, Texas.

Photo 9 – Derailment due to dilapidated siding conditions. Commerce, Texas.

Photo 10 – Poor siding conditions. Sulphur Springs, Texas.

Photo 11 – Poor track alignment and vegetation encroachments on siding. Commerce, Texas.

Photo 12 – Vegetation encroachments on main line. Hopkins County, Texas.