

---

## Special Provision to Item 778

### Concrete Rail Repair

---



Item 778, "Concrete Rail Repair" of the Standard Specifications is amended with respect to the clauses cited below. No other clauses or requirements of this Item are waived or changed.

**Article 778.1, "Description"** is voided and replaced by the following:

Repair or replace damaged concrete railing on bridges, culverts, parapet walls, retaining walls, or other structures as shown on the plans and as directed.

**Article 778.4, "Work Methods"** is supplemented by the following::

Provide and apply paint in accordance with Item 427 "Surface Finishes for Concrete" to match color of existing rail if the existing rail was previously painted.

**Article 778.5, "Payment"** is voided and replaced by the following:

The work performed and materials furnished in accordance with this Item and measured as provided under "Measurement" will be paid for at the unit price bid for "Concrete Rail Repair," "Concrete Rail Replacement," "Concrete Post Repair," and "Concrete Post Replacement" of the type identified. This price is full compensation for removing and reinstalling metal rail components; for breaking back and restoring concrete rail; for furnishing and placing all materials; for salvaging and reinstalling existing expansion joints; for painting the rail if required, and for all labor, tools, equipment, and incidentals necessary to complete the work.