



MEMORANDUM

TO: All District Engineers

DATE: August 21, 2008

FROM: William R. Cox, P.E.
Carlos A. Lopez, P.E.

William R. Cox, P.E.
Carlos A. Lopez, P.E.

SUBJECT: Revised Overhead Sign Bridge and
Cantilever Overhead Sign Support
Standard Sheets

Due to conversion issues from Microstation J to Microstation V8, revisions to several Overhead Sign Bridge (OSB) and Cantilever Overhead Sign Support (COSS) standard sheets are required. The OSB and COSS standard sheets, drawings 32 thru 44 and 61 thru 65 published November 26, 2007, should not be used.

BRG has revised the OSB and COSS standard sheets, drawings 32 thru 44 and 61 thru 65. The revised standard sheets are available in MicroStation and PDF formats at the following web address:

<http://www.dot.state.tx.us/insdtdot/orgchart/cmd/cserve/standard/toc.htm>

If you have any questions or comments concerning the revised standards, please contact Michael Chacon (TRF) at (512) 416-3120, or Tim Bradberry (BRG) at (512) 416-2179.

cc: AUD
ADM
CST
DES
MNT
TTA
Tim Bradberry, P.E., BRG
Michael A. Chacon, P.E., TRF