



RWYS 4-22
AND 17R-35L
HAVE BAK-14
ARRESTING
BARRIERS

Lat: N 29° 36.44'
Lon: W 95° 09.53'

Elev: 32' MSL
TPA: See Remarks

Sectional: HOUSTON
Downtown to Apt: 15 nm/SE

Owner: CITY OF HOUSTON
16930 JFK BLVD
HOUSTON TX 77032
Phone: 281-233-3000

Manager: BRIAN RINEHART
BLDG 510 ELLINGTON FIELD
HOUSTON TX 77034
713-847-4200

ATTENDANCE SCHEDULE: 24 HRS

FUEL: JET A 100LL

REPAIRS: Airframe: MAJOR Power Plant: MAJOR

LIGHTS: DSK-DWN **ATIS:** 135.575 **UNICOM:** 122.95 **TWR:** 126.05

REMARKS: FOOD-LODGING (8 MI); TAXI; CAR RENTAL; AIRPORT NOISE PROCEDURES; FLT INST; (MC, VISA, AMEX) TPA: VFR RECTANGULAR 1100 (1068); OVERHEAD 1600 (1568); LGT ACFT 600 (568)

FIXED BASE OPERATOR: SOUTHWEST SERVICES 484-6551; ROCKETMAN

