



Lat: N 30° 21.45'
Lon: W 97° 59.67'

Elev: 909' MSL
TPA: 1900 (991)

Sectional: SAN ANTONIO
Downtown to Apt: 2 nm/SW

Owner: LAKEWAY AIRPARK, INC
 115 FLYING SCOT
 AUSTIN, TX 78734
Phone: 512-261-4385
Web: www.3r9.org

Manager: AIRPORT BOARD
 115 FLYING SCOT
 AUSTIN, TX 78734
 512-261-4385

ATTENDANCE SCHEDULE: UNATTENDED

FUEL: 100LL SELF SERVE

REPAIRS: Airframe: NONE Power Plant: NONE

LIGHTS: NONE

UNICOM/CTAF: 123.0

REMARKS: RENTAL CAR BY PRIOR ARRANGEMENT; FOOD-LODGING (1 MI);
 TOUCH AND GO TRAFFIC PROHIBITED; WATCH FOR DEER ON RWY;
 WATCH FOR CULVERTS WEST OF RWY; LANDING FEE FOR TURBINES
 & JETS; NO OPERATIONS SS-SR

FIXED BASE OPERATORS: NONE

