


DECATUR, HERITAGE CREEK AIRSTRIP (58T)

UPDATED: 10/9/2013



Lat: N 33° 10.12'
Lon: W 97° 29.05'

Elev: 883' MSL
TPA: STD

Sectional: DALLAS-FT WORTH
Downtown to Apt: 09 nm/SE

Owner: HERITAGE CREEK PILOTS ASSOC
 1040 HERITAGE CREEK DRIVE
 RHOME, TX 76078
Phone: 940-319-6261

Manager: GREELY WEBB
 1040 HERITAGE CREEK DRIVE
 RHOME, TX 76078
 940-319-6261

ATTENDANCE SCHEDULE: UNATTENDED

FUEL: NONE

REPAIRS: Airframe: NONE Power Plant: NONE

LIGHTS: DSK-DWN RDO/CTL

UNICOM/CTAF: 122.9

REMARKS: FOOD-LODGING (8 MI); GLIDER & ULTRALIGHT ACTIVITY;
 PARACHUTE ACTIVITY 5 MI SW

FIXED BASE OPERATORS: NONE

