



Lat: N 33° 22.64'
Lon: W 96° 43.73'

Elev: 750' MSL
TPA: STD

Sectional: DALLAS-FT WORTH
Downtown to Apt: 05 nm/SW

Owner: BOBBY BISHOP
 8955 CR 135
 CELINA TX 75009
Phone: 214-204-4408

Manager: BOBBY BISHOP
 8955 CR 135
 CELINA TX 75009
Email: bobby@texasturbines.com

ATTENDANCE SCHEDULE: UNATTENDED

FUEL: NONE

REPAIRS: Airframe: NONE Power Plant: NONE

LIGHTS: NONE **CTAF:** 122.9

REMARKS: OWNER LIVES ON AIRPORT

FIXED BASE OPERATORS: NONE

