
Special Provision to Item 361

Full-Depth Repair of Concrete Pavement



Item 361 "Repair of Concrete Pavement of the Standard Specifications is amended with respect to the clauses cited below. No other clauses or requirements of this Item are waived or changed.

Article 361.5. "Measurement", is voided and replaced by the following:

361.5.1. Repair of Concrete Pavement (Half-Depth). This Item will be measured by the square yard in place of the completed concrete surface area repaired.

361.5.2. Repair of Concrete Pavement (Full-Depth). This Item will be measured by the cubic yard of material complete in place of the completed concrete area repaired. Volume will be computed on the basis of the measured area in place and the average depth as calculated according to the plans.